




Stockholm, November 2025

SCUBA medium pressure hoses

This safety advisory applies to SCUBA medium pressure hoses with UNF 3/8 threaded nipples supplied for use with Interspiro SCUBA equipment. Affected hoses are marked with the production batch numbers 2400 to 2540 on the hose sleeve.



Interspiro has recently received a very limited number of reports regarding nipple breakage on medium pressure hoses. No failures have occurred during diving operations.

To maintain operational safety and reliability, the medium pressure hoses must be replaced. This work must be carried out by a certified service technician. Replacement hoses will be provided free of charge to affected customers. The replacement shall be completed as soon as practically possible.

When assembling new hoses, the tightening torque shall be 8 Nm.

Our top priority is always the safety of our customers and end users. We apologize for the inconvenience this issue is causing.