

PRODUCT RECALL NOTICE


CMC CSR² PULLEYS AND PULLEY SYSTEMS

CMC Part Numbers: 300343, 300342, 500102, 500103, 501201, 501301

Affected Lot Numbers: 18116-01 through 18138-28

Dear Valued Customer,

During routine testing, CMC has learned that a small number of CSR² Pulleys manufactured in April and May 2018 while strong, may not meet the minimum breaking strength (MBS) required for certification due to a manufacturing error. Products potentially impacted are the CSR² Pulley (PN# 300343) and CSR² Double Pulley (PN# 300342) with Lot Numbers **18116-01** through **18138-28**. These pulleys are most commonly sold assembled in systems: CSR² Pulley System 13mm (PN# 500102), and CSR² Pulley System 11mm (PN# 500103); and found in kits, Confined Space Entry Kit (PN# 501201), and Confined Space Rescue Team Kit (PN# 501301).



REQUIRED ACTION

- Check all CSR² pulleys to identify any with affected lot numbers 18116-01 through 18138-28.
- Immediately remove any affected CSR² products from service.
- Contact CMC Customer Support at (800) 235-5741, (805) 562-9120, or via email at recall@cmcpro.com to receive a free shipping label and initiate the return process.
- Return the affected product directly to CMC for a no-cost full repair or replacement of the product.

Thank you for your continued support and trust!

The CMC Rescue Team